



How to Comply with C&D Recycling Requirements

Guidance for Contractors

Generators of construction & demolition debris are responsible for managing waste associated with their projects.

These items must be kept separate from landfill-bound trash:

- **Plywood – clean & unpainted**
 - **OSB – clean & unpainted**
 - **Asphalt shingles**
 - **Scrap metal**
 - **Unpainted lumber & pallets**
 - **Unpainted Drywall**
 - **Cardboard**
-

Facilities accepting C&D materials:

- Myers C&D Recycling Center, 216 Red Can Drive (off Rathe Rd), Colchester, 802-655-4312
- Casella's All Cycle Transfer Station, 220 Ave B, Williston, 802-651-5412. Accepts material from Casella hauling only.
- CSWD Williston DOC, 1492 Redmond Road, Williston, 802-872-7109. Accepts loads of a cubic yard or less.

See attached for additional options.



Best Practices for Best Results

Step 1

Designate a point person for waste and recycling related questions and duties.

Step 2

Identify all materials that will be generated on site.

Step 3

Determine on-site storage and container needs. Recommendations:

- Two containers minimum—one for recyclable C&D, one for waste.
- Separate container/collection area for drywall during drywall phase. Drywall must not be collected with other recyclable materials as the dust will contaminate all materials.
- Separate container/collection area for cardboard during finishing stages (countertops, cabinets, fixtures, flooring). Cardboard must be kept clean and dry.
- 32/64 gallon blue recycling cart for mandatory recyclables like drink bottles, office paper etc.

Step 4

Contact a hauler and/or recycler that can take the materials

Step 5

Separate materials into dedicated containers on site OR

Arrange for recycler pickup and separation of mixed material.

Step 6

Keep records for materials recycled and disposed. At a minimum, you will want to keep weight tickets for the duration of the project.

